DANGER

AUTHORIZED PERSONNEL ONLY

LIQUID NITROGEN

THERMAL & ASPHYXIATION RISK

PPE REQUIRED AT ALL TIMES



- Insulated Gloves
 - Face Shield
 - Lab Coat



SPILL PROCEDURE: Leave the area immediately.

Contact Security at (402) 559-5555